

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

EXHIBIT 1

Site Accessibility Evaluation Dated February 10, 2020

(Excerpts)

Site Accessibility Evaluation

Americans with Disabilities Act And Title 24 And Part 2 - California Building Code



ABC Printing

**1090 S Milpitas Blvd
Milpitas, CA 95035**

CASp Evaluation

Inspection Date: 01/20/2020

Inspector: Craig Lobnow

Prepared By



**(833) 776 - 2277
ProCASp.com**

Parking

Finding: 1

The striping and markings for the accessible parking stall, loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.

The slope of the parking space and access aisle were found to be in compliance.

2019 CBC 11B Section 11B-502.3.3

Access aisles shall be marked with a blue painted borderline around their perimeter. The area within the blue borderlines shall be marked with hatched lines a maximum of 36 inches (914 mm) on center in a color contrasting with that of the aisle surface, preferably blue or white. The words "NO PARKING" shall be painted on the surface within each access aisle in white letters a minimum of 12 inches (305 mm) in height and located to be visible from the adjacent vehicular way. Access aisle markings may extend beyond the minimum required length.

2010 ADAS Section 502.3.3

Access aisles shall be marked so as to discourage parking in them.

Citation:

2019 CBC 11B Section: 11B-502.3.3

2010 ADAS Section: 502.3.3

